

SECRET

OUT51974

P 032324Z

1963 OCT 4 01 33Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBKG/15TH AF, MARCH AFB, RIVERSIDE, CALIF

RUWGAA/2D RTS, BARKSDALE AFB, LA

RUWGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

SECRETCITE CIA-Z-924

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4) 2D AF
(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 11 WAS USED IN MISSION 3737 FLOWN ON 1 OCTOBER
1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE IS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9L SIDE: A SERIES OF PLUS DENSITY DOTS ARE PRESENT
5.5" FROM THE OUTBOARD EDGE ALONG WITH MANY PLUS DENSITY STREAKS
2.2" LONG FROM FRAME 315 TO FRAME 325. PINHOLES ARE NOTED IN
FRAMES 533, 827, 838, 849, 886 917, 1118 AND
1193. CINCH MARKS ASSOCIATED WITH HEAT SPLICES ARE PRESENT IN

4 OCT 1963

HFS

CJS

GFC

DHS

ACL

Grace (File)

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

FRAMES 679, 1498 AND 1499. THERE ARE BLISTERS IN FRAMES 795, 855, 1173, 1503, 2263 AND 2269. MINUS DENSITY COMETS ARE NOTED IN FRAMES 913 THROUGH 916, 938, 1498 AND 2114. MINUS DENSITY DOTS, 1.55" APART AND 3.2" FROM THE INBOARD EDGE ARE LOCATED IN FRAMES 1192, 1193 AND 1194. RANDOM MINUS DENSITY DOTS AND STREAKS ARE NOTED IN FRAME 1498. THERE IS INBOARD EDGE FOG IN FRAMES 2310 THROUGH 2314.

C. C. 9R SIDE: A VERY FAINT MINUS DENSITY STREAK IS PRESENT INTERMITTENTLY 0.1" FROM THE INBOARD EDGE THROUGHOUT THE MISSION. SCRATCHES AND ABRASIONS ASSOCIATED WITH A TEAR ARE PRESENT IN FRAMES 393, 394 AND 395. THERE ARE CRIMPS AND HANDLING MARKS ASSOCIATED WITH HEAT SPLICES IN FRAMES 134, 267, 532, 788 AND 725. EMULSION DIGS ARE NOTED IN FRAMES 2150, 2151, 2152 AND 2181. BLISTERS ARE NOTED IN FRAMES 1993, 2073, 2088 AND 2108.

D. BOTH SIDES: THE VERTICAL INDICATOR DID NOT OPERATE ON THIS MISSION AND THE POSITION INDICATOR MARKS ARE UNDEREXPOSED. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES OTHER THAN THOSE NOTED. THERE IS A TOTAL OF 2314 EXPOSURES IN THIS MISSION.

3. POSITIVE:

A. PI SUITABILITY IS GOOD; HOWEVER, WATER SPOTS ARE PRESENT INTERMITTENTLY THROUGHOUT THE MISSION. (EXAMPLE: FRAME 210 ON THE 9R SIDE)

B. CLOUDS COVERED 75 PERCENT OF THE MISSION.

S E C R E T

END OF MESSAGE